NATIONAL AVIATION FACILITIES EXPERIMENTAL CENTER ATL--ETC F/G 17/7 EVALUATION OF A RED-SILICONE-COATED VISUAL APPROACH SLOPE INDIC--ETC(U) AD-A035 141 JAN 77 R E JOHNSTON FAA/RD-76/201 UNCLASSIFIED FAA-NA-76-31 NL OF 1 AD-A 035 141 END DATE FILMED 3-7-77 NTIS

U.S. DEPARTMENT OF COMMERCE National Technical Information Service

AD-A035 141

EVALUATION OF A RED-SILICONE-COATED VISUAL APPROACH SLOPE INDICATOR (VASI) LENS

NATIONAL AVIATION FACILITIES EXPERIMENTAL CENTER ATLANTIC CITY, NEW JERSEY

JANUARY 1977




EVALUATION OF A RED-SILICONE-COATED VISUAL APPROACH SLOPE INDICATOR (VASI) LENS

Raymond E. Johnston



January 1977

FINAL REPORT



Document is available to the public through the National Technical Information Service Springfield, Virginia 22151

Prepared for INFORMATION SERVICE
U.S. DEPARTMENT OF COMMERCE
U.S. DEPARTMENT OF COMMERCE

U. S. DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

Systems Research & Development Service Washington, D.C. 20590

NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

Technical Report Documentation Page

1. Report No. FAA-RD-76-201	2. Government Accession No.	3. Recipient's Catalog No.			
4. Title and Subtitle EVALUATION OF A RED-SILICONE SLOPE INDICATOR	5. Report Date January 1977 6. Performing Organization Code				
7. Author(s) Raymond E.	8. Performing Organization Report No. FAA-NA-76-31				
9. Performing Organization Name and Addre Federal Aviation Administrat National Aviation Facilities Atlantic City, New Jersey O	10. Work Unit No. (TRAIS) 11. Contract or Grant No. 071-312-070 13. Type of Report and Period Covered				
12. Sponsoring Agency Name and Address U.S. Department of Transport Federal Aviation Administrat Systems Research and Develop Washington, D.C. 20590	Final September 1975 - July 1976 14. Sponsoring Agency Code				

15. Supplementary Notes

16. Abstract

The subject effort was to test and evaluate the results of a new method of producing the red/white color-coded signal used in a Visual Approach Slope Indicator (VASI) system. The present system utilizes a split lens assembly to produce the color coding, which consists of a clear lens segment and a red lens segment, the clear being somewhat smaller than the red, to construct one single VASI lens assembly. A new method of providing the signal was developed by coating the upper part of a circular clear lens with a heat-resistant red-silicone-pigment paint, leaving the lower part clear to transmit the white signal. Laboratory and field tests conducted on the coated lens resulted in no appreciable deterioration of the red signal; therefore, it was determined that this method of providing the signal was comparable to the split lens assembly. The results of the tests indicate that this method of producing the signal would be suitable for present and future VASI systems.

17. Key Words		18. Distribution Statement							
Visual Approach Slope Indic Landing Guidance	ators	Document is available to the public through the National Technical Information Service,							
Airport Visual Aids Approach Indicators Navigational Aid		Springfield, Virginia 22151							
19. Security Classif. (of this report) Unclassified	20. Security Classifi		21. No. of Pages	350/3.00					

Form DOT F 1700.7 (8-72)

Reproduction of completed page authorized

METRIC CONVERSION FACTORS


j		.5.1		R i			•	£ '}	Ť					8 4					# 1	K 6	. 3	£'	ě					1			1
		nohes	,	yands				squere inches	squere miles	scres				Ounces	short tone				fluid ounces	pints	gellons	cubic feet	cubic yards				Fahrenheit temperature		22 22 091] :	
rsions from Motris	LENGTH	50.0	33	2 2	1	AREA		0.16		2.5		MASS (weight)		0.036	7:		VOLUME		0.03	2.1	0.26	38	1.3		TEMPERATURE (exact)		9/5 (then add 32)		986	3,5	
Approximate Conversions from Metric Measures		millimeters	meters	meters				square centimeters	square kilometers	hectares (10,000 m ²)		•		grams	Kilograms	(By coor) sautor			milliliters	liters	liters	cubic meters	cubic meters		TEMP		Celsius		9F 32	22-	
j		E	ĒE	e J	ı		,	E ~E	~ 5	2					6.				Ē.	-		e.	m _E				ů		4	1 0	-
EZ ZZ	12 	oz 6		8T	2		91 	51		**		13			11		 	6		•		-	9		5			3	z	Cu ^T	
s ' , , , ,	- -		 '''	'l' ₇	["	""	"	'l' 6	.1.	['l'	1"1	' ' 5	' '	ין ין יויין ו	' '	" "	' ''I'	 	' 'I	"	' '	""	' '	' '		'	יייןיין	' '	' ' ' 1	' inches	
	STATE		5	5	e 5			7 W5	~E	~ _E ?	5	2		•	64	-			Ē	E	Ē -	-	-		E	E		၁့		.286,	
Messures	1		Centimeters	centimeters	meters			square centimeters	square meters	square meters	Square Allometers	nectares		grams	kilograms	tonnes			milliliters	milliliters	lifore	liters	liters	liters	cubic meters	CODIC HEIGHT		Celsius	temperature	ables, see NBS Misc. Publ. 286.	
Approximate Conversions to Metric Measures	Multiply by	LENGTH	.2.5	30	6.0 9,1		ANEA	6.5	60.0	8.0	0.7	•	MASS (weight)	28	0.45	6.0	VOLUME		s	5 5	30	0.47	96.0	3.8	0.03	6,70	TEMPERATURE (exact)	5/9 (after	subtracting 32)	risions and more detailed to D Catalog No. C13,10:286.	
Approximate Com	When You Know	-	inches	100	yards		1	square inches	square feet	sduare yards	sense mies		*	ounces	spunod	short tons (2000 lb)			teaspoons	tablespoons	tinid ounces	pints	quarts	gallons	cubic reet	ent age	TEMP	Fahrenheit	temperature	1) in 1.254 (exactiv), For other exact conversions and more detailed tables, Units of Weights and Nessures, Price \$2.25, SD Catalog No. C13.10.286.	
	ļ				2 E			~	~ ·	, Š	ī			8	•				180	ded	8 .	. %	10	es.	£ "}	2				"1 in # 2.54 lex	


:=

TABLE OF CONTENTS

	Page
INTRODUCTION	1
Purpose Background Description of Equipment	1 1 1
TEST PROCEDURES	2
Laboratory Tests Field Tests	2 2
TEST RESULTS	2
SUMMARY OF RESULTS	5
CONCLUSION	5

APPENDIX - Photometric Characteristics of Red-Silicone-Coated VASI Lenses before and after a 6-Month Field Test and a 31-Day Laboratory Test Period





LIST OF ILLUSTRATIONS

Figure		Page
1	Comparison Between Split Lens Assembly and Red-Silicone- Coated Lens	3
A-1	Vertical Distribution Curve at Zero Degrees Azimuth for Initial and Final Tests	A-4

LIST OF TABLES

Table		Page
1	Transmittance (T) of Red Sectors of Silicone-Coated VASI Filters and CIE Chromaticity Coordinates x and y for the Initial and Final Test Periods	4
A-1	Red-Silicone-Coated Lens, Initial Measurements of Intensity in Candela Versus Azimuth and Elevation Angles in Degrees	A-2
A-2	Red-Silicone-Coated Lens, Final Measurements of Intensity in Candela Versus Azimuth and Elevation Angles in Degrees	A-3

INTRODUCTION

PURPOSE.

The purpose of this activity was to evaluate the results of a new method of producing the red/white color-coded signal used in a Visual Approach Slope Indicator (VASI) system by use of a red-silicone-pigment coating applied to the upper portion of a circular clear lens.

BACKGROUND.

The VASI is a navigational aid that provides a visual glide slope indication for a pilot during his approach to the runway touchdown zone under visual flight rules (VFR) weather conditions.

This signal is provided to the pilot by the transmission of a pair of red/white color-coded signals located approximately 15 meters off the edge of the runway, having a longitudinal separation between light signals of approximately 150 meters. The light signals are aligned so as to present to the pilot on approach a white/red signal when on the proper glide slope, a white/white signal when above the glide slope, and a red/red signal when below the proper glide slope.

The system is a valuable aid as a method of defining a safe visual approach slope clearance over obstructions that cannot themselves be obstruction lighted. It further provides aiming-point information, thus alleviating the possibility of over-shoots and undershoots. The number of light units or boxes that make up a VASI system varies between 2 and 16 boxes at airports where straight-in approaches could be made.

DESCRIPTION OF EQUIPMENT.

This effort is concerned with the evaluation of a silcone-coated lens assembly. The present lens assembly utilizes a split lens system, with the upper portion red and the lower portion clear. The manufacture of this type of lens assembly is time consuming and costly, in part, because the red portion is larger in area than the clear; therefore, that part of the red lens which is not used is wasted.

A new method of providing the red signal has been developed by coating the upper portion of a circular clear lens with a heat-resistant red-silicone-pigment paint. Several of these lenses were delivered to NAFEC for photometric and environmental testing to determine if the lens will meet the color requirements for a VASI system.

Figure 1 is a photograph exhibiting both the split lens assembly shown on the left and the coated lens shown on the right. It can be seen in the photograph that the red segment is somewhat larger than the clear. When installed in the

system, the red segment is positioned above the clear so that when both the upwind box, the one furthest from the threshold, and the downwind box, the one near the threshold, are properly aligned, the VASI will transmit the proper signal for a fly-up, on glide slope, or a fly-down indication.

TEST PROCEDURES

LABORATORY TESTS.

Silicone-coated lenses were delivered to the Metrology Laboratory at the National Aviation Facilities Experimental Center (NAFEC) for optical testing. The tests consisted of chromaticity measurements and light distribution measurements of the red portion of the lens. The tests were conducted using three 200-watt PAR 64, 6.6-ampere General Electric Quartzline lamps at maximum rated output. The lamps and lenses were installed in a standard three-lamp VASI unit. The optical tests were conducted before and after a 31-day life test period and a 6-month field test period to determine if the red-silicone-pigment coating remained within the CIE color coordinate boundries, x=0.680/0.695 y=0.296/0.316, with a transmittance net loss less than 10 percent after the lens stabilized at normal operating temperature.

The light distribution measurements were conducted to determine if there was any appreciable change in output of the red signal between the initial and final tests which would indicate a degradation of the silicone paint.


FIELD TESTS.

The field tests were conducted primarily to determine what effect actual weather conditions would have on the pigment coating of the lens, such as blistering or peeling, due to natural environmental conditions. The three lenses were installed in a VASI unit located adjacent to runway 13 at NAFEC. The tests were run for a period of 6 months. At the end of the test period, the lenses were returned to the Metrology Laboratory to conduct the final optical tests.

TEST RESULTS

Table 1 show the results of the chromaticity measurements for the initial and final tests. It can be seen that the transmittance (T) remained unchanged for the tests.

The table indicates a slight change in the x and y coordinates for each of the three lenses tested. When removed from the field it was noted that the lenses had experienced minor scratches or abrasions that were apparently caused by small field creatures entering the VASI unit or possibly dirt and sand blown into the VASI unit by jet aircraft.



COMPARISON BETWEEN SPLIT LENS ASSEMBLY AND RED-SILICONE-COATED LENS FIGURE 1.

76-31-1

TABLE 1. TRANSMITTANCE (T) OF RED SECTORS OF SILICONE-COATED VASI FILTERS AND CIE CHROMATICITY COORDINATES x AND y FOR THE INITIAL AND FINAL TEST PERIODS

Filter	Initi	al Measu	rements	Final Measuremen					
No.		х	у	<u>T</u>	<u> </u>	у			
1	0.15	0.684	0.310	0.15	0.683	0.311			
2	.17	.679	.313	.17	.677	.314			
3	.17	.680	.312	.17	.680	.313			

NOTE: x coordinate minimums should be 0.680. Two lenses above are within the 0.680 minimums, and one lens below minimum.

During the initial chromaticity measurements, one of the lenses did not quite meet the color specifications as required. This was evidently due to an insufficient amount of coating applied to the lens during the processing.

The curves plotted on the graph in the appendix, figure A-1, were derived from the tables A-1 and A-2, the initial and final distribution measurements. The output in candelas versus the vertical distribution in degrees was taken at the midpoint or zero azmuth as shown in the tables. There was a slight degradation of the coating, as can be seen in figure A-1.

Because there was no appreciable change in color, as evidenced by the laboratory and field tests, it was decided that flight tests of the system were unwarranted. However, during several flight tests of other activities at NAFEC observers requested to look at the VASI on runway 13. Their opinions were that there was no difference between the red signal of the standard VASI and that of the coated VASI.

SUMMARY OF RESULTS

As evidenced from the results of the laboratory tests and the field tests, the coated lens experienced negligible degradation. There was no peeling or blistering of the paint due to exposure to changes in atmospheric conditions when installed in the field. The minor scratches or abrasions of the coating were determined negligible and not contributable to any change in color. Visual observations of the system showed that there was no detectable difference in signal output.

CONCLUSION

It was concluded from the results of the laboratory and field tests performed on the silicone-coated VASI lens that this method of providing a red signal for a standard VASI was found satisfactory and may be used in lieu of the standard split lens assembly.

APPENDIX A

PHOTOMETRIC CHARACTERISTICS OF RED-SILICONE-COATED VASI LENSES BEFORE AND AFTER A 6-MONTH FIELD TEST AND A 31-DAY LABORATORY TEST PERIOD

Comparison between initial and final vertical distribution curves plotted from the tabular data of tables A-1 and A-2 is made. Curves are taken through zero azimuth for figure A-1.

TABLE A-1. RED-SILICONE-COATED LENS, INITIAL MEASUREMENTS OF INTENSITY IN CANDELA VERSUS AZIMUTH AND ELEVATION ANGLES IN DEGREES

ELEVATION

AZIMUTH	-5.0	-4.0	-3.0	-2.0	-1.0	.0
-13.0 -12.0 -11.0		2 0 2 0 4 1	103 103 123	185 206 267	309 391 494	309 350 453
-10.0 -9.0	20	61	144 226	391 679	700	576 824
-8.0 -7.0	20	8 2 1 2 3	453 927	1339	1833	1174
-6.0 -5.0 -4.0		185 226 267	1627 2286 2863	4017 5644 6859	4037 5232 6262	2224 2801 3337
-3.0 -2.0	20 20	288 309	3172 3275	7725 8178	7107 7642	3708 3975
-1.0 .0 1.0	20	329 329 309	3296 3337 3378	8363 8425 8466	7992 8157 8198	4161 4284 4305
2.0		329 309	3296 3213	8404	8116 7992	4264
5.0		309 288	3110	7951	7704	3975
6.0 7.0 8.0		267 206 164	2575 2018 1380	6489 5047 3646	6200 5026 3790	3254 2698 2121
9.0		103	782 370	2245 1236	2678 1812	1586
11.0 12.0 13.0	20	61 61 41	226 164 123	638 350 247	1153 741 494	865 638 453
14.0		41	123	206	370	350

⁽⁻⁾ Sign on azimuth reads degrees that lens is turned right of photometer. No sign on azimuth indicates zero turn through 14° to the left of photometer.

⁽⁻⁾ Sign on elevation indicates a depression of the lens below the horizontal.


TABLE A-2. RED-SILICONE-COATED LENS, FINAL MEASUREMENTS OF INTENSITY IN CANDELA VERSUS AZIMUTH AND ELEVATION ANGLES IN DEGREES

ELEVATION

	-5.0	-4.0	-3.0	-2.0	-1.0	.0
AZIMUTH						
-13.0	20	41	92	175	319	298
-12.0		41	113	216	381	360
-11.0		61	123	278	525	463
-10.0		51	154	401	731	597
-9.0	10	72	236	731	1122	834
-8.0	10	82	463	1369	1977	1225
-7.0	10	123	1019	2678	3059	1709
-6.0	10	185	1689	4315	4253	2276
-5.0	10	288	2441	6077	5397	2884
-4.0	10	278	3028	7251	6550	3440
-3.0	10	309	3316	8064	7498	3831
-2.0	20	319	3419	8538	8003	4120
-1.0	20	350	3471	8724	8301	4326
.0		339	3532	8785	8476	4439
1.0	10	350	3574	8837	8476	4470
2.0	20	339	3522	8755	8425	4439
3.0	10	339	3460	8579	8281	4315
4.0	20	319	3388	8332	7941	4150
5.0		309	3223	7838	7323	3852
6.0	10	298	2873	6870	6406	3429
7.0	10	236	2338	5489	5253	2945
8.0	10	175	1658	3893	3965	2235
9.0	30	133	916	2317	2822	1730
10.0	10	92	453	1256	1998	1277
11.0	10	61	236	628	1225	937
12.0	10	61	164	381	762	679
13.0	10	51	144	267	535	494
14.0	10	51	113	216	391	339

⁽⁻⁾ Sign on azimuth reads degrees that lens is turned right of photometer. No sign on azimuth indicates zero turn through 14° to the left of photometer.

⁽⁻⁾ Sign on elevation indicates a depression of the lens below the horizontal.



VERTICAL DISTRIBUTION CURVE AT ZERO DEGREES AZIMUTH FOR INITIAL AND FINAL TESTS FIGURE A-1.